



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 JAC JS4

INTELLIGENT | 33,452 KM

VIN: LJ12EKS35P4734077

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Apple play

Enjoy your drive with apple play

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	33452	 Specs	Yes
 Engine	1.5L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	LJ12EKS35P4734077		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
360 degree Camera		Parking Sensors Rear	
Reverse Camera		Front Camera	
Side Camera		Airbag Driver Front	
Airbag Passenger Front		ABS	
 Comfort & Convenience			

Climate Control AC	✓	Cruise Control	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Windows Rear	✓		
 Exteriors			
Roof Rails	✓	Running Lights	✓
 Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door

Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Acid Marks/ Bird Dropping > 5mm, Paint Chip-off > 5mm 

Rear left door
Panel: Scuffing 

Rear right door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off > 5mm 

Fenders Condition

Left Fender

Condition: Acid Marks/ Bird Dropping < 20mm 

Right Fender
Right Fender: Acid Marks/ Bird Dropping 

Quarter Panels Condition

Left Quarter Panel 

Right Quarter Panel
Condition: Acid Marks/ Bird Dropping, Light Scuffing 

Rear Bumper Condition

Rear Bumper

Rear Bumper: Scuffing > 80mm, Fully Repainted, Refurbished to RTA standards, Dent > 50mm, Crack/ Misaligned 

Hood Condition

Hood

Bonnet: Acid Marks/ Bird Dropping > 5mm, Light Scuffing < 50mm 

Roof Condition

Roof 

Running Board Condition

Left Running Board 

Right Running Board 

Sunroof Glass Condition (If Equipped)

Sun Roof Glass 

Windshield Condition

Front Windshield

Condition: Air Bubbles, Front Wiper blades need replacement



Rear Windshield

Wiper blade damaged



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Right Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Monogram



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Transmission Operation

Gear Shifting



Drive Axle



Steering, Suspension & Brakes

Brake System

Parking Brake



Brake Master Cylinder



Brake Fluid	✓
Suspension	
Shock Absorbers	✓

Electricals, Controls & Lights

Keys		
Master Key	!	
Central Locking Not Working		
Dashboard		
Instrument Panel	✓	
Controls	✓	Cruise Control ✓
Infotainment Display	✓	Music System ✓
Camera	✓	
Lights		
Headlight	✓	Interior Lights ✓
Tail Light Cluster		
Right Tail Lamp: Crack / Fair Use Wear > 5mm	!	Daylight Running Lights ✓
Air Conditioning		
AC Cooling	✓	AC System Leaks ✓
Rear Blower Switch	✓	
Power/ Manual Windows	✓	

Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted	!	Gear Shift Knob: Knob Fair Use Wear	!
Cup Holder	✓	Steering Wheel	!
		Steering Wheel Fair Use Wear > 80 mm	
Sunvisor	✓	Seat Upholstery	✓

Manual Seat Movement		Seat Belts	
Head Rest		Door Controls And Trim	
Carpet		Headliner	
Front Left Floor Mat: Smudge/Burn/Crack			
Rear View Mirror		Toolkit	
Damaged Mirror Casing			

Tyres

Tyres Condition			
Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Life remaining			
LHS Front Tyre	<45%	LHS Rear Tyre	<65%
RHS Front Tyre	<45%	RHS Rear Tyre	<55%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE