



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



COMING SOON



2025 PEUGEOT 408

GT | 36,373 KM

VIN: VR3F3EGP8SY500024

## Car highlights



### Great condition

Car has low imperfections



### Cruise control

Cruise control to drive with ease & comfort

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K  
applicable



### Apple play

Enjoy your drive with apple play



### Amazing Comfort

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                     |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|---------------------|
|  Kilometers       | 36373             |  Specs             | Yes                 |
|  Engine           | 1.6L              |  Option Type       | Semi Loaded         |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive   |
|  Body Type        | COUPE             |  Fuel              | Petrol              |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Blue |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 6 Airbags           |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys              |
|  VIN number     | VR3F3EGP8SY500024 |                                                                                                     |                     |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                       |                                                                                     |                               |                                                                                       |
|-------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------|---------------------------------------------------------------------------------------|
|  Safety & Security |                                                                                     |                               |                                                                                       |
| 360 degree Camera                                                                                     |  | Lane Departure Warning System |  |
| Navigation                                                                                            |  | Parking Sensors Front         |  |
| Parking Sensors Rear                                                                                  |  | Reverse Camera                |  |
| Collision Warning System                                                                              |  | Airbag Sides                  |  |
| Airbag Curtain Shield                                                                                 |  | Airbag Driver Front           |  |

|                                                                                                                    |   |                                     |   |
|--------------------------------------------------------------------------------------------------------------------|---|-------------------------------------|---|
| Airbag Passenger Front                                                                                             | ✓ | ABS                                 | ✓ |
|  <b>Comfort &amp; Convenience</b> |   |                                     |   |
| Climate Control AC                                                                                                 | ✓ | Cruise Control                      | ✓ |
| Power Window front - Drivers Side                                                                                  | ✓ | Power Window front - Passenger Side | ✓ |
| Power Tailgate/ Power Trunk                                                                                        | ✓ | Power Windows Rear                  | ✓ |
|  <b>Exteriors</b>                 |   |                                     |   |
| Fog Light Front                                                                                                    | ✓ |                                     |   |
|  <b>Performance</b>               |   |                                     |   |
| Paddle Shift                                                                                                       | ✓ | Hydraulic Suspensions               | ✓ |
|  <b>Entertainment</b>             |   |                                     |   |
| Bluetooth Player                                                                                                   | ✓ | Apple Play                          | ✓ |
| Android Auto Play                                                                                                  | ✓ |                                     |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

Doors condition

Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Roof Condition

Roof



Running Board Condition

Left Running Board



Right Running Board



Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



|                            |   |                         |
|----------------------------|---|-------------------------|
| Cowl Top                   |   |                         |
| Cowl Top                   | ✓ |                         |
| Rear View Mirror Condition |   |                         |
| Left Hand Side Mirror      | ✓ | Right Side Mirror ✓     |
| Alloy Wheel/ Rim           |   |                         |
| Left Front Alloy/ Rim      | ✓ | Left Rear Alloy/ Rim ✓  |
| Right Front Alloy/ Rim     | ✓ | Right Rear Alloy/ Rim ✓ |
| Monogram                   | ✓ |                         |
| Panel Condition            |   |                         |
| Rear Trunk Panel           | ✓ |                         |

## Engine & Transmission

|                                |   |                      |
|--------------------------------|---|----------------------|
| Engine                         |   |                      |
| Engine Body                    | ✓ | Engine Performance ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System ✓     |
| Turbocharger/ Supercharger     | ✓ | Radiator Condition ✓ |
| Radiator Coolant               | ✓ |                      |
| Transmission Operation         |   |                      |
| Gear Shifting                  | ✓ | Drive Axle ✓         |

## Steering, Suspension & Brakes

|                 |   |                         |
|-----------------|---|-------------------------|
| Steering        |   |                         |
| Steering wheel  | ✓ |                         |
| Brake System    |   |                         |
| Parking Brake   | ✓ | Brake Master Cylinder ✓ |
| Brake Fluid     | ✓ |                         |
| Suspension      |   |                         |
| Shock Absorbers | ✓ |                         |

## Electricals, Controls & Lights

|                      |   |                         |   |
|----------------------|---|-------------------------|---|
| Keys                 |   |                         |   |
| Master Key           | ✓ |                         |   |
| Dashboard            |   |                         |   |
| Instrument Panel     | ✓ |                         |   |
| Controls             | ✓ | Cruise Control          | ✓ |
| Infotainment Display | ✓ | Music System            | ✓ |
| Camera               | ✓ |                         |   |
| Lights               |   |                         |   |
| Headlight            | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster   | ✓ | Daylight Running Lights | ✓ |
| Air Conditioning     |   |                         |   |
| AC Cooling           | ✓ | AC System Leaks         | ✓ |
| Rear Blower Switch   | ✓ | Rear Left AC Vent       | ✓ |
| Rear Entertainment   | ✓ | Power/ Manual Windows   | ✓ |
| Memory Seats         | ✓ |                         |   |

## Interiors & Luggage

|                                |   |                        |   |
|--------------------------------|---|------------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console        | ✓ |
| Cup Holder                     | ✓ | Steering Wheel         | ✓ |
| Sunvisor                       | ✓ | Seat Upholstery        | ✓ |
| Manual Seat Movement           | ✓ | Seat Belts             | ✓ |
| Head Rest                      | ✓ | Door Controls And Trim | ✓ |
| Carpet                         | ✓ | Headliner              | ✓ |
| Rear View Mirror               | ✓ | Toolkit                | ✓ |

## Tyres

### Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



### Life remaining

LHS Front Tyre

<55%

LHS Rear Tyre

<55%

RHS Front Tyre

<55%

RHS Rear Tyre

<55%

Spare Tyre

<55%





## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE