



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2020 MITSUBISHI ATTRAGE**

**GLX MID | 115,793 KM**

VIN: MMDAF26J9LH009642

## **Car highlights**

### **Fuel Efficient**

Fuel efficient with 20.2 km/L



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Bluetooth**

Enjoy your drive with bluetooth



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                     |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|---------------------|
|  Kilometers       | 115793            |  Specs             | Yes                 |
|  Engine           | 1.2L              |  Option Type       | Semi Loaded         |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive   |
|  Body Type        | SEDAN             | Fuel Efficiency                                                                                     | 20.2 km/L mileage   |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Grey |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags           |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys              |
|  VIN number     | MMDAF26J9LH009642 |                                                                                                     |                     |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                           |                                                                                     |                                                                                                                         |
|-----------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------|
|  Exteriors             |                                                                                     |                                                                                                                         |
| Fog Light Front                                                                                           |  |                                                                                                                         |
|  Comfort & Convenience |                                                                                     |                                                                                                                         |
| Cruise Control                                                                                            |  | Power Window front - Drivers Side  |
| Power Window front - Passenger Side                                                                       |  | Power Windows Rear                 |
|  Safety & Security     |                                                                                     |                                                                                                                         |

|                                                                                                          |                                                                                                        |
|----------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------|
|                                                                                                          |                                                                                                        |
| Reverse Camera           | Airbag Driver Front  |
| Airbag Passenger Front  | ABS                 |
|  <b>Entertainment</b>   |                                                                                                        |
| Bluetooth Player        |                                                                                                        |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                  |                                                                                   |                |                                                                                     |
|------------------|-----------------------------------------------------------------------------------|----------------|-------------------------------------------------------------------------------------|
| Front right door |  | Rear left door |  |
|------------------|-----------------------------------------------------------------------------------|----------------|-------------------------------------------------------------------------------------|

|                              |                                                                                   |
|------------------------------|-----------------------------------------------------------------------------------|
| Rear right door              |  |
| Panel: Light Scuffing < 50mm |                                                                                   |

### Fenders Condition

|             |                                                                                   |              |                                                                                     |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|
| Left Fender |  | Right Fender |  |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|

### Quarter Panels Condition

|                     |                                                                                   |                     |                                                                                     |
|---------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|
| Left Quarter Panel  |  | Right Quarter Panel |  |
| Condition: Scuffing |                                                                                   |                     |                                                                                     |

### Rear Bumper Condition

|                                                     |                                                                                     |
|-----------------------------------------------------|-------------------------------------------------------------------------------------|
| Rear Bumper                                         |                                                                                     |
| Rear Bumper: Light Scuffing < 80mm, Fully Repainted |  |

### Hood Condition

|                               |                                                                                     |
|-------------------------------|-------------------------------------------------------------------------------------|
| Hood                          |                                                                                     |
| Bonnet: Light Scuffing < 50mm |  |

### Running Board Condition

|                    |                                                                                     |                     |                                                                                       |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|
| Left Running Board |  | Right Running Board |  |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|

### Sunroof Glass Condition (If Equipped)

|                |                                                                                     |
|----------------|-------------------------------------------------------------------------------------|
| Sun Roof Glass |  |
|----------------|-------------------------------------------------------------------------------------|

### Windshield Condition

|                  |                                                                                     |                 |                                                                                       |
|------------------|-------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------------------------------|
| Front Windshield |  | Rear Windshield |  |
|------------------|-------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------------------------------|

### Structural Assessment

|                   |                                                                                     |            |                                                                                       |
|-------------------|-------------------------------------------------------------------------------------|------------|---------------------------------------------------------------------------------------|
| Chassis Condition |  | Boot Floor |  |
|-------------------|-------------------------------------------------------------------------------------|------------|---------------------------------------------------------------------------------------|

|                    |                                                                                     |                              |                                                                                       |
|--------------------|-------------------------------------------------------------------------------------|------------------------------|---------------------------------------------------------------------------------------|
| Firewall Condition |  | Head Light Support Condition |  |
|--------------------|-------------------------------------------------------------------------------------|------------------------------|---------------------------------------------------------------------------------------|

Cowl Top

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Cowl Top               | ✓ |                       |   |
| Alloy Wheel/ Rim       |   |                       |   |
| Left Front Alloy/ Rim  | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Panel Condition        |   |                       |   |
| Rear Trunk Panel       | ✓ |                       |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Turbocharger/ Supercharger     | ✓ | Radiator Condition | ✓ |
| Radiator Coolant               | ✓ |                    |   |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Steering        |   |                       |   |
| Steering wheel  | ✓ |                       |   |
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

|                  |   |                      |   |
|------------------|---|----------------------|---|
| Keys             |   |                      |   |
| Master Key       | ✓ |                      |   |
| Dashboard        |   |                      |   |
| Instrument Panel | ✓ |                      |   |
| Controls         | ✓ | Infotainment Display | ✓ |

|                                                  |   |                                  |   |
|--------------------------------------------------|---|----------------------------------|---|
| Music System                                     | ✓ | Camera                           | ⓘ |
|                                                  |   | Reverse Camera: External Fitment |   |
| Lights                                           |   |                                  |   |
| Headlight                                        |   |                                  |   |
| Left: Head light bracket broken                  | ⓘ | Tail Light Cluster               | ✓ |
| Daylight Running Lights                          | ✓ |                                  |   |
| Air Conditioning                                 |   |                                  |   |
| AC Cooling                                       |   |                                  |   |
| AC Temperature: Missing control knobs/<br>Broken | ⓘ |                                  |   |
| Power/ Manual Windows                            | ✓ | Memory Seats                     | ✓ |

### Interiors & Luggage

|                                |   |                 |   |
|--------------------------------|---|-----------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Steering Wheel                 | ✓ | Headliner       | ✓ |

### Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <55% | LHS Rear Tyre             | <55% |
| RHS Front Tyre             | <55% | RHS Rear Tyre             | <55% |
| Spare Tyre                 | <65% |                           |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE