



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 MITSUBISHI MONTERO SPORT

GLS MID | 79,737 KM

VIN: MMEMC21XXHH003630

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera, Parking Sensors Rear

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Music System

Enjoy your drive with music system



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	79737	 Specs	Yes
 Engine	3.0L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Rear Wheel Drive
 Body Type	SUV	Fuel Efficiency	10.0 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Red
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	MMEMC21XXHH003630		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Power Window front - Drivers Side		Power Window front - Passenger Side	
Power Windows Rear			
 Exteriors			
Fog Light Front		Roof Rails	

Running Lights		
 Safety & Security		
Parking Sensors Rear		Reverse Camera
Airbag Curtain Shield		Airbag Driver Front
Airbag Passenger Front		ABS
 Entertainment		
Rear Seat Entertainment		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door



Rear left door

Panel: Scuffing



Rear right door

Panel: Scuffing > 50mm



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Rear Bumper Condition

Rear Bumper

Rear Bumper: Fully Repainted, Crack/

Misaligned



Hood Condition

Hood

Bonnet: Scuffing > 50mm, Acid Marks/ Bird

Dropping < 5mm



Running Board Condition

Left Running Board



Right Running Board



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top

Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Right Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Monogram	✓		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Performance	✓	Engine Oil (Condition & Level)	✓
Exhaust System	✓	Radiator Coolant	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid			
Front Brake Pad Thickness < 3mm	!		

Electricals, Controls & Lights

Keys			
Master Key	✓		
Dashboard			
Instrument Panel			
Malfunction Indication Lights: Service warning	!		
Light			
Controls	✓	Cruise Control	✓

Infotainment Display	✓	Music System	✓
Camera	✓		
Lights			
Headlight	!	Interior Lights	✓
Left: Low Brightness lamps			
Tail Light Cluster	✓	Daylight Running Lights	✓
Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC System Leaks	✓
Rear Blower Switch	✓	Rear Left AC Vent	!
		LHS Crack/Fair Use Wear	
Rear Entertainment	✓	Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel			
Dashboard Upholstery: Scuffing/	!	Central Console	✓
Disfiguration/ Melted > 80 mm			
Cup Holder	✓	Steering Wheel	✓
Sunvisor			
Left: Sunvisor LHS Vanity Mirror Cover	!	Seat Upholstery	✓
Damage, Sunvisor RHS Vanity Mirror Cover			
Damage			
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	!	Door Controls And Trim	✓
Driver Seat: Not Functioning Properly			
Carpet	!	Headliner	✓
Front Left Floor Mat: Floor Mat Missing			
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Rear Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Life remaining			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<55%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE