



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





2019 HYUNDAI ACCENT

COMFORT | 131,382 KM

VIN: MALC741C9KM080335

Car highlights



Sunroof

This car has a sunroof



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	131382	 Specs	Yes
 Engine	1.6L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Silver
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	MALC741C9KM080335		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Power Window front - Drivers Side	
Power Window front - Passenger Side		Power Windows Rear	
 Safety & Security			
Parking Sensors Rear		Reverse Camera	
Airbag Driver Front		Airbag Passenger Front	

ABS



Entertainment

Bluetooth Player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door

Panel: Light Scuffing < 50mm, Acid Marks/
Bird Dropping < 5mm 

Rear left door 

Rear right door

Panel: Low Visual Dent < 30mm, Light
Scuffing < 50mm 

Fenders Condition

Left Fender

Condition: Light Scuffing, Paint Chip-off, Low
Visual Dent 

Right Fender
Right Fender: Paint Chip-off 

Quarter Panels Condition

Left Quarter Panel
Condition: Scuffing 

Right Quarter Panel
Condition: Scuffing/ Scratch, Dent 

Rear Bumper Condition

Rear Bumper

Rear Bumper: Fully Repainted, Replaced,
Scuffing > 80mm 

Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm, Light Scuffing
< 50mm 

Roof Condition

Roof 

Running Board Condition

Left Running Board 

Right Running Board 

Sunroof Glass Condition (If Equipped)

Sun Roof Glass 

Windshield Condition

Front Windshield			
Condition: Front Wiper blades need replacement, Driver Side/Stone Chip Mark<5mm, Air Bubbles	⚠	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	⚠		
Fair Use Wear/Crack<5mm			
Rear View Mirror Condition			
Left Hand Side Mirror	⚠	Right Side Mirror	✓
Body: Not Folding			
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	⚠	Right Rear Alloy/ Rim	✓
Rim: Alloy Face Scuffing			
Monogram	✓		
Panel Condition			
Rear Trunk Panel	✓		

🔧 Engine & Transmission

Engine			
Engine Performance	✓	Engine Oil (Condition & Level)	✓
Exhaust System	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓

🚗 Steering, Suspension & Brakes

Brake System			
Parking Brake	✓	Brake Fluid	✓
Suspension			

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key

Central Locking Not Working



Dashboard

Instrument Panel



Controls



Cruise Control



Infotainment Display



Music System



Camera



Lights

Headlight

Left: Low Brightness lamps



Interior Lights



Tail Light Cluster



Air Conditioning

AC Cooling



AC System Leaks



Rear Blower Switch



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/

Disfiguration/ Melted, Minor Scuffing/ Crack/

Fair Use Wear



Central Console

Gear Shift Knob: Knob Fair Use Wear



Cup Holder



Steering Wheel

Steering Wheel Fair Use Wear



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts

Driver Seat: Seat Belt Twisted



Head Rest



Door Controls And Trim



Carpet		Headliner	
Rear View Mirror		Toolkit	
Damaged Mirror Casing			

Tyres

Tyres Condition

Left Hand Side Rear Tyre		Right Hand Side Front Tyre	
Right Hand Side Rear Tyre		Spare Tyre	
Life remaining			
LHS Front Tyre	<75%	LHS Rear Tyre	<65%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE