



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



COMING SOON



2019 MITSUBISHI MONTERO SPORT

GLS MID | 106,935 KM

VIN: MMEMC71X7KH011141

### Car highlights



#### **Great condition**

Car has low imperfections



#### **Cruise control**

Cruise control to drive with ease & comfort

#### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



#### **Bluetooth**

Enjoy your drive with bluetooth



#### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 106935            |  Specs             | Yes                  |
|  Engine           | 3.0L              |  Option Type       | Semi Loaded          |
|  Transmission     | Automatic         |  Drive             | Four Wheel Drive     |
|  Body Type        | SUV               | Fuel Efficiency                                                                                     | 10.0 km/L mileage    |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags            |
|  Seating Capacity | 7 Seats           |  Number of keys    | 1 Keys               |
|  VIN number     | MMEMC71X7KH011141 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                           |                                                                                     |                                   |                                                                                       |
|-----------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------------------|---------------------------------------------------------------------------------------|
|  Exteriors             |                                                                                     |                                   |                                                                                       |
| Fog Light Front                                                                                           |  |                                   |                                                                                       |
|  Comfort & Convenience |                                                                                     |                                   |                                                                                       |
| Cruise Control                                                                                            |  | Power Window front - Drivers Side |  |
| Power Window front - Passenger Side                                                                       |  | Power Windows Rear                |  |
|  Safety & Security     |                                                                                     |                                   |                                                                                       |

|                                                                                                        |   |                      |   |
|--------------------------------------------------------------------------------------------------------|---|----------------------|---|
| Navigation                                                                                             | ✓ | Parking Sensors Rear | ✓ |
| Reverse Camera                                                                                         | ✓ | Airbag Driver Front  | ✓ |
| Airbag Passenger Front                                                                                 | ✓ | ABS                  | ✓ |
|  <b>Performance</b>   |   |                      |   |
| Paddle Shift                                                                                           | ✓ | Hill Descent Control | ✓ |
| Differential Locks                                                                                     | ✓ |                      |   |
|  <b>Entertainment</b> |   |                      |   |
| Bluetooth Player                                                                                       | ✓ |                      |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

|                                                 |              |                     |              |
|-------------------------------------------------|--------------|---------------------|--------------|
| Doors condition                                 |              |                     |              |
| Front right door                                | <div>✓</div> | Rear left door      | <div>✓</div> |
| Rear right door                                 | <div>✓</div> |                     |              |
| Fenders Condition                               |              |                     |              |
| Left Fender                                     | <div>✓</div> | Right Fender        | <div>✓</div> |
| Quarter Panels Condition                        |              |                     |              |
| Left Quarter Panel                              | <div>✓</div> | Right Quarter Panel | <div>✓</div> |
| Rear Bumper Condition                           |              |                     |              |
| Rear Bumper                                     |              |                     |              |
| Rear Bumper: Dent < 50mm, Light Scuffing < 80mm |              | <div>!</div>        |              |
| Hood Condition                                  |              |                     |              |
| Hood                                            | <div>✓</div> |                     |              |
| Running Board Condition                         |              |                     |              |
| Left Running Board                              | <div>✓</div> | Right Running Board | <div>✓</div> |
| Sunroof Glass Condition (If Equipped)           |              |                     |              |
| Sun Roof Glass                                  | <div>✓</div> |                     |              |
| Windshield Condition                            |              |                     |              |
| Front Windshield                                | <div>✓</div> | Rear Windshield     | <div>✓</div> |
| Structural Assessment                           |              |                     |              |
| Chassis Condition                               | <div>✓</div> | Boot Floor          | <div>✓</div> |
| Head Light Support Condition                    | <div>✓</div> |                     |              |
| Cowl Top                                        |              |                     |              |
| Cowl Top                                        | <div>✓</div> |                     |              |

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Alloy Wheel/ Rim       |   |                       |   |
| Left Front Alloy/ Rim  | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Panel Condition        |   |                       |   |
| Rear Trunk Panel       | ✓ |                       |   |

## Engine & Transmission

|                                       |   |                    |   |
|---------------------------------------|---|--------------------|---|
| Engine                                |   |                    |   |
| Engine Body                           |   |                    |   |
| Damage & Leaks: Timing cover repaired | ! | Engine Performance | ✓ |
| Engine Oil (Condition & Level)        | ✓ | Radiator Condition | ✓ |
| Radiator Coolant                      | ✓ |                    |   |
| Transmission Operation                |   |                    |   |
| Gear Shifting                         |   |                    |   |
| Mountings weak                        | ! | Drive Axle         | ✓ |
| 4*4 Condition (If Applicable)         | ✓ |                    |   |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Steering        |   |                       |   |
| Steering wheel  | ✓ |                       |   |
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

|                  |   |                      |   |
|------------------|---|----------------------|---|
| Keys             |   |                      |   |
| Master Key       | ✓ |                      |   |
| Dashboard        |   |                      |   |
| Instrument Panel | ✓ |                      |   |
| Controls         | ✓ | Infotainment Display | ✓ |

|                         |   |                    |   |
|-------------------------|---|--------------------|---|
| Music System            | ✓ | Camera             | ✓ |
| Lights                  |   |                    |   |
| Headlight               | ✓ | Tail Light Cluster | ✓ |
| Daylight Running Lights | ✓ |                    |   |
| Air Conditioning        |   |                    |   |
| AC Cooling              | ✓ |                    |   |
| Power/ Manual Windows   | ✓ | Memory Seats       | ✓ |

### Interiors & Luggage

|                                |   |                 |   |
|--------------------------------|---|-----------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Steering Wheel                 | ✓ | Headliner       | ✓ |

### Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <73% | LHS Rear Tyre             | <73% |
| RHS Front Tyre             | <73% | RHS Rear Tyre             | <73% |
| Spare Tyre                 | <65% |                           |      |



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE