



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.



COMING SOON



2019 TOYOTA RAV4

ADVENTURE | 129,637 KM

VIN: JTMJ13FVXKJ018525

Car highlights



Great condition

Car has low imperfections



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	129637	 Specs	Yes
 Engine	2.5L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	Fuel Efficiency	12.0 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Green
 Interior Trim	Leather Trim	 Number of Airbags	7 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	JTMJ13FVXKJ018525		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Power Window front - Drivers Side		Power Window front - Passenger Side	
Power Tailgate/ Power Trunk		Power Windows Rear	
 Exteriors			
Fog Light Front		Roof Rails	

Running Lights	✓	
 Safety & Security		
Parking Sensors Front	✓	Parking Sensors Rear ✓
Reverse Camera	✓	Airbag Sides ✓
Airbag Curtain Shield	✓	Airbag Knees ✓
Airbag Driver Front	✓	Airbag Passenger Front ✓
ABS	✓	
 Performance		
Hill Descent Control	✓	
 Entertainment		
Bluetooth Player	✓	Apple Play ✓
Android Auto Play	✓	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition	
Front right door Panel: Light Scuffing < 50mm	
Rear left door	
Rear right door	
Fenders Condition	
Left Fender	
Right Fender	
Quarter Panels Condition	
Left Quarter Panel	
Right Quarter Panel	
Rear Bumper Condition	
Rear Bumper Rear Bumper: Fully Repainted, Light Scuffing < 80mm	
Hood Condition	
Hood	
Running Board Condition	
Left Running Board	
Right Running Board	
Sunroof Glass Condition (If Equipped)	
Sun Roof Glass	
Windshield Condition	
Front Windshield	
Rear Windshield	
Structural Assessment	
Chassis Condition	
Boot Floor	
Head Light Support Condition	
Cowl Top	
Cowl Top	

Alloy Wheel/ Rim		
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim ✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim ✓
Panel Condition		
Rear Trunk Panel	✓	

Engine & Transmission

Engine		
Engine Body	✓	Engine Performance ✓
Engine Oil (Condition & Level)	✓	Radiator Condition ✓
Radiator Coolant	✓	
Transmission Operation		
Gear Shifting	✓	Drive Axle ✓

Steering, Suspension & Brakes

Brake System		
Parking Brake	✓	Brake Master Cylinder ✓
Suspension		
Shock Absorbers	✓	

Electricals, Controls & Lights

Keys		
Master Key	✓	
Dashboard		
Instrument Panel	✓	
Controls	✓	Infotainment Display ✓
Music System	✓	Camera ✓
Lights		
Headlight	✓	Tail Light Cluster ✓
Daylight Running Lights	✓	

Air Conditioning

AC Cooling



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Steering Wheel



Headliner



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<90%

LHS Rear Tyre

<55%

RHS Front Tyre

<90%

RHS Rear Tyre

<55%

Spare Tyre

<15%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE