



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



COMING SOON



2023 CHRYSLER 300

S | 94,303 KM

VIN: 2C3CCABG1PH605112

## Car highlights



### Power packed

Engine size of 4.0 Litres & 6.0 cylinders



### Adaptive cruise control

Adaptive cruise control to drive with ease & comfort

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable



### Apple play

Enjoy your drive with apple play



### Amazing Comfort

Memory Seats, Ventilated Seats

Basic Details

|                                                                                                    |                   |                                                                                                     |                     |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|---------------------|
|  Kilometers       | 94303             |  Specs             | Yes                 |
|  Engine           | 4.0L              |  Option Type       | Fully Loaded        |
|  Transmission     | Automatic         |  Drive             | Rear Wheel Drive    |
|  Body Type        | SEDAN             |  Fuel              | Petrol              |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Blue |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 7 Airbags           |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys              |
|  VIN number     | 2C3CCABG1PH605112 |                                                                                                     |                     |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                       |                                                                                     |                               |                                                                                       |
|-------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------|---------------------------------------------------------------------------------------|
|  Safety & Security |                                                                                     |                               |                                                                                       |
| Adaptive cruise control                                                                               |  | Lane Departure Warning System |  |
| Navigation                                                                                            |  | Parking Sensors Front         |  |
| Parking Sensors Rear                                                                                  |  | Reverse Camera                |  |
| Blind Spot Monitor                                                                                    |  | Airbag Sides                  |  |
| Airbag Curtain Shield                                                                                 |  | Airbag Knees                  |  |

|                                                                                                                    |   |                                   |   |
|--------------------------------------------------------------------------------------------------------------------|---|-----------------------------------|---|
| Airbag Driver Front                                                                                                | ✓ | Airbag Passenger Front            | ✓ |
| ABS                                                                                                                | ✓ |                                   |   |
|  <b>Comfort &amp; Convenience</b> |   |                                   |   |
| Climate Control AC                                                                                                 | ✓ | Cruise Control                    | ✓ |
| Memory Seats                                                                                                       | ✓ | Power Window front - Drivers Side | ✓ |
| Power Window front - Passenger Side                                                                                | ✓ | Ventilated Seat                   | ✓ |
| Power Windows Rear                                                                                                 | ✓ |                                   |   |
|  <b>Exteriors</b>                 |   |                                   |   |
| Fog Light Front                                                                                                    | ✓ | Running Lights                    | ✓ |
| Rear Bumper Spoiler                                                                                                | ✓ |                                   |   |
|  <b>Performance</b>             |   |                                   |   |
| Paddle Shift                                                                                                       | ✓ |                                   |   |
|  <b>Entertainment</b>           |   |                                   |   |
| Rear Seat Entertainment                                                                                            | ✓ | Bluetooth Player                  | ✓ |
| Apple Play                                                                                                         | ✓ |                                   |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

#### Front right door

Panel: Scuffing > 50mm, Paint Chip-off > 5mm



#### Rear left door



#### Rear right door

Panel: Scuffing > 50mm, Paint Chip-off > 5mm



### Fenders Condition

#### Left Fender



#### Right Fender



### Quarter Panels Condition

#### Left Quarter Panel



Right Quarter Panel  
Condition: Scuffing/ Scratch



### Rear Bumper Condition

#### Rear Bumper



### Hood Condition

#### Hood



### Running Board Condition

#### Left Running Board



#### Right Running Board



### Sunroof Glass Condition (If Equipped)

#### Sun Roof Glass



### Windshield Condition

#### Front Windshield

Condition: Front Wiper blades need replacement



#### Rear Windshield



### Structural Assessment

#### Chassis Condition



#### Apron



#### Boot Floor



#### Firewall Condition



|                              |   |                       |   |
|------------------------------|---|-----------------------|---|
| Head Light Support Condition | ✓ |                       |   |
| Cowl Top                     |   |                       |   |
| Cowl Top                     | ✓ |                       |   |
| Rear View Mirror Condition   |   |                       |   |
| Left Hand Side Mirror        | ✓ | Right Side Mirror     | ✓ |
| Alloy Wheel/ Rim             |   |                       |   |
| Left Front Alloy/ Rim        | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim       | ✓ | Right Rear Alloy/ Rim | ✓ |
| Grill Condition              |   |                       |   |
| Colour Faded                 | ! | Monogram              | ✓ |
| Panel Condition              |   |                       |   |
| Rear Trunk Panel             | ✓ |                       |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Transmission Operation         |   |                    |   |
| Drive Axle                     | ✓ |                    |   |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid     | ✓ |                       |   |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

|            |   |
|------------|---|
| Keys       |   |
| Master Key | ✓ |

|                                          |   |                         |   |
|------------------------------------------|---|-------------------------|---|
| Dashboard                                |   |                         |   |
| Instrument Panel                         | ✓ |                         |   |
| Controls                                 | ! | Cruise Control          | ✓ |
| Power Seat: Adjuster Control Not Working |   |                         |   |
| Infotainment Display                     | ✓ | Music System            | ✓ |
| Camera                                   | ! |                         |   |
| Reverse Camera: Lens Damaged/ Blurred    |   |                         |   |
| Lights                                   |   |                         |   |
| Headlight                                | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster                       | ✓ | Daylight Running Lights | ✓ |
| Fog Lights                               | ✓ |                         |   |
| Air Conditioning                         |   |                         |   |
| AC Cooling                               | ✓ | AC System Leaks         | ✓ |
| Rear Blower Switch                       | ✓ |                         |   |
| Power/ Manual Windows                    | ✓ | Memory Seats            | ✓ |

## Interiors & Luggage

|                                |   |                                                   |   |
|--------------------------------|---|---------------------------------------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console                                   | ✓ |
| Cup Holder                     | ✓ | Steering Wheel                                    | ✓ |
| Sunvisor                       | ✓ | Seat Upholstery                                   | ✓ |
| Manual Seat Movement           | ✓ | Seat Belts                                        | ✓ |
| Head Rest                      | ✓ | Door Controls And Trim                            | ✓ |
| Carpet                         | ✓ | Headliner                                         | ✓ |
|                                |   | Toolkit                                           |   |
| Rear View Mirror               | ✓ | Jack Availability: Warning Triangle Not Available | ! |

## Tyres

|                            |                                                                                   |                           |                                                                                     |
|----------------------------|-----------------------------------------------------------------------------------|---------------------------|-------------------------------------------------------------------------------------|
| Tyres Condition            |                                                                                   |                           |                                                                                     |
| Left Hand Side Front Tyre  |  | Left Hand Side Rear Tyre  |  |
| Right Hand Side Front Tyre |  | Right Hand Side Rear Tyre |  |
| Spare Tyre                 |  |                           |                                                                                     |
| Life remaining             |                                                                                   |                           |                                                                                     |
| LHS Front Tyre             | <75%                                                                              | LHS Rear Tyre             | <75%                                                                                |
| RHS Front Tyre             | <75%                                                                              | RHS Rear Tyre             | <75%                                                                                |
| Spare Tyre                 | <55%                                                                              |                           |                                                                                     |





## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE