



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2024 MG ONE**

**LUXURY | 24,138 KM**

VIN: LSJW94U96RN014872

## Car highlights

### **Service History**

Service history available



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Android Auto**

Enjoy your drive with Android Auto



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 24138             |  Specs             | Yes                  |
|  Engine           | 1.5L              |  Option Type       | Fully Loaded         |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SUV               | Fuel Efficiency                                                                                     | 14.7 km/L mileage    |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Black |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 6 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys               |
|  VIN number     | LSJW94U96RN014872 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                       |                                                                                     |                       |                                                                                       |
|-------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------|---------------------------------------------------------------------------------------|
|  Safety & Security |                                                                                     |                       |                                                                                       |
| 360 degree Camera                                                                                     |  | Parking Sensors Front |  |
| Parking Sensors Rear                                                                                  |  | Reverse Camera        |  |
| Blind Spot Monitor                                                                                    |  | Front Camera          |  |
| Side Camera                                                                                           |  | Airbag Sides          |  |
| Airbag Curtain Shield                                                                                 |  | Airbag Driver Front   |  |

|                                                                                                                    |   |                                     |   |
|--------------------------------------------------------------------------------------------------------------------|---|-------------------------------------|---|
| Airbag Passenger Front                                                                                             | ✓ | ABS                                 | ✓ |
|  <b>Comfort &amp; Convenience</b> |   |                                     |   |
| Climate Control AC                                                                                                 | ✓ | Cruise Control                      | ✓ |
| Power Window front - Drivers Side                                                                                  | ✓ | Power Window front - Passenger Side | ✓ |
| Cool Box                                                                                                           | ✓ | Power Windows Rear                  | ✓ |
|  <b>Exteriors</b>                 |   |                                     |   |
| Fog Light Front                                                                                                    | ✓ | Running Lights                      | ✓ |
|  <b>Entertainment</b>             |   |                                     |   |
| Bluetooth Player                                                                                                   | ✓ | Android Auto Play                   | ✓ |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                                   |                                                                                   |                |                                                                                     |
|-----------------------------------|-----------------------------------------------------------------------------------|----------------|-------------------------------------------------------------------------------------|
| Front right door                  |  | Rear left door |  |
| Panel: Low Visibility Dent < 30mm |                                                                                   |                |                                                                                     |

|                 |                                                                                   |
|-----------------|-----------------------------------------------------------------------------------|
| Rear right door |  |
|-----------------|-----------------------------------------------------------------------------------|

### Fenders Condition

|             |                                                                                   |              |                                                                                     |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|
| Left Fender |  | Right Fender |  |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|

### Quarter Panels Condition

|                    |                                                                                   |                     |                                                                                     |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|

### Rear Bumper Condition

|             |                                                                                     |
|-------------|-------------------------------------------------------------------------------------|
| Rear Bumper |  |
|-------------|-------------------------------------------------------------------------------------|

### Hood Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Hood |  |
|------|-------------------------------------------------------------------------------------|

### Running Board Condition

|                    |                                                                                     |                     |                                                                                       |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|
| Left Running Board |  | Right Running Board |  |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|

### Sunroof Glass Condition (If Equipped)

|                |                                                                                     |
|----------------|-------------------------------------------------------------------------------------|
| Sun Roof Glass |  |
|----------------|-------------------------------------------------------------------------------------|

### Windshield Condition

|                  |                                                                                     |                 |                                                                                       |
|------------------|-------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------------------------------|
| Front Windshield |  | Rear Windshield |  |
|------------------|-------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------------------------------|

### Structural Assessment

|                   |                                                                                     |            |                                                                                       |
|-------------------|-------------------------------------------------------------------------------------|------------|---------------------------------------------------------------------------------------|
| Chassis Condition |  | Boot Floor |  |
|-------------------|-------------------------------------------------------------------------------------|------------|---------------------------------------------------------------------------------------|

|                              |                                                                                     |
|------------------------------|-------------------------------------------------------------------------------------|
| Head Light Support Condition |  |
|------------------------------|-------------------------------------------------------------------------------------|

### Cowl Top

|          |                                                                                     |
|----------|-------------------------------------------------------------------------------------|
| Cowl Top |  |
|----------|-------------------------------------------------------------------------------------|

### Alloy Wheel/ Rim

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Left Front Alloy/ Rim  | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Panel Condition        |   |                       |   |
| Rear Trunk Panel       | ✓ |                       |   |

## Engine & Transmission

|                                |   |                            |   |
|--------------------------------|---|----------------------------|---|
| Engine                         |   |                            |   |
| Engine Body                    | ✓ | Engine Performance         | ✓ |
| Engine Oil (Condition & Level) | ✓ | Turbocharger/ Supercharger | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant           | ✓ |
| Transmission Operation         |   |                            |   |
| Gear Shifting                  | ✓ | Drive Axle                 | ✓ |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

|                         |   |                      |   |
|-------------------------|---|----------------------|---|
| Keys                    |   |                      |   |
| Master Key              | ✓ |                      |   |
| Dashboard               |   |                      |   |
| Instrument Panel        | ✓ |                      |   |
| Controls                | ✓ | Infotainment Display | ✓ |
| Music System            | ✓ | Camera               | ✓ |
| Lights                  |   |                      |   |
| Headlight               | ✓ | Tail Light Cluster   | ✓ |
| Daylight Running Lights | ✓ |                      |   |
| Air Conditioning        |   |                      |   |

AC Cooling 

Power/ Manual Windows 

---

 **Interiors & Luggage**

Dashboard And Instrument Panel  Central Console 

Steering Wheel  Headliner 

---

 **Tyres**

Tyres Condition

Left Hand Side Front Tyre  Left Hand Side Rear Tyre 

Right Hand Side Front Tyre  Right Hand Side Rear Tyre 

Spare Tyre 

Life remaining

LHS Front Tyre <73% LHS Rear Tyre <73%

RHS Front Tyre <73% RHS Rear Tyre <73%

Spare Tyre <55%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE