



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2024 TOYOTA PRADO**

**TXR | 24,738 KM**

VIN: JTEAA9AJXRK003529

## Car highlights



### **Great condition**

Car has low imperfections



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Music System**

Enjoy your drive with music system



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 24738             |  Specs             | Yes                  |
|  Engine           | 2.4L              |  Option Type       | Basic                |
|  Transmission     | Automatic         |  Drive             | Four Wheel Drive     |
|  Body Type        | SUV               |  Fuel              | Petrol               |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Black |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 2 Airbags            |
|  Seating Capacity | 7 Seats           |  Number of keys    | 2 Keys               |
|  VIN number      | JTEAA9AJXRK003529 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                     |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                     |                                                                                       |
| Climate Control AC                                                                                                   |  | Cruise Control                      |  |
| Power Window front - Drivers Side                                                                                    |  | Power Window front - Passenger Side |  |
| Power Windows Rear                                                                                                   |  |                                     |                                                                                       |
|  <b>Exteriors</b>                 |                                                                                     |                                     |                                                                                       |
| Fog Light Front                                                                                                      |  | Roof Rails                          |  |

|                                                                                                                |   |                         |
|----------------------------------------------------------------------------------------------------------------|---|-------------------------|
| Running Lights                                                                                                 | ✓ |                         |
|  <b>Safety &amp; Security</b> |   |                         |
| Navigation                                                                                                     | ✓ | Parking Sensors Front ✓ |
| Parking Sensors Rear                                                                                           | ✓ | Reverse Camera ✓        |
| Airbag Knees                                                                                                   | ✓ | Airbag Driver Front ✓   |
| Airbag Passenger Front                                                                                         | ✓ | ABS ✓                   |
|  <b>Performance</b>           |   |                         |
| Hydraulic Suspensions                                                                                          | ✓ | Hill Descent Control ✓  |
| Differential Locks                                                                                             | ✓ |                         |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

Doors condition

Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Running Board Condition

Left Running Board



Right Running Board



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Boot Floor



Head Light Support Condition



Cowl Top

Cowl Top



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



|                  |   |  |
|------------------|---|--|
| Grill Condition  | ✓ |  |
| Panel Condition  |   |  |
| Rear Trunk Panel | ✓ |  |

## Engine & Transmission

|                                |   |                              |
|--------------------------------|---|------------------------------|
| Engine                         |   |                              |
| Engine Body                    | ✓ | Engine Performance ✓         |
| Engine Oil (Condition & Level) | ✓ | Turbocharger/ Supercharger ✓ |
| Radiator Condition             | ✓ | Radiator Coolant ✓           |
| Transmission Operation         |   |                              |
| Gear Shifting                  | ✓ | Drive Axle ✓                 |
| 4*4 Condition (If Applicable)  | ✓ |                              |

## Steering, Suspension & Brakes

|                 |   |                         |
|-----------------|---|-------------------------|
| Steering        |   |                         |
| Steering wheel  | ✓ |                         |
| Brake System    |   |                         |
| Parking Brake   | ✓ | Brake Master Cylinder ✓ |
| Suspension      |   |                         |
| Shock Absorbers | ✓ |                         |

## Electricals, Controls & Lights

|                  |   |                        |
|------------------|---|------------------------|
| Keys             |   |                        |
| Master Key       | ✓ |                        |
| Dashboard        |   |                        |
| Instrument Panel | ✓ |                        |
| Controls         | ✓ | Infotainment Display ✓ |
| Music System     | ✓ | Camera ✓               |
| Lights           |   |                        |

|                         |   |                    |   |
|-------------------------|---|--------------------|---|
| Headlight               | ✓ | Tail Light Cluster | ✓ |
| Daylight Running Lights | ✓ |                    |   |
| Air Conditioning        |   |                    |   |
| AC Cooling              | ✓ |                    |   |
| Power/ Manual Windows   | ✓ |                    |   |

## Interiors & Luggage

|                                |   |                 |   |
|--------------------------------|---|-----------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Steering Wheel                 | ✓ | Headliner       | ✓ |

## Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <73% | LHS Rear Tyre             | <73% |
| RHS Front Tyre             | <73% | RHS Rear Tyre             | <73% |
| Spare Tyre                 | <73% |                           |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE