



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





2020 HYUNDAI ACCENT

GL | 144,669 KM

VIN: MALC741C6LM188204

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Rear

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Music System

Enjoy your drive with music system



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	144669	 Specs	Yes
 Engine	1.6L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	Fuel Efficiency	16.5 km/L mileage
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color Silver
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	MALC741C6LM188204		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Power Window front - Drivers Side	
Power Window front - Passenger Side		Power Windows Rear	
 Safety & Security			
Parking Sensors Rear		Airbag Driver Front	
Airbag Passenger Front		ABS	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door

Panel: Light Scuffing < 50mm, Low Visibility
Dent < 30mm 

Rear left door

Panel: Scuffing 

Rear right door

Panel: Scuffing > 50mm, Low Visual Dent < 30mm 

Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel

Condition: Scuffing 

Right Quarter Panel

Condition: Light Scuffing 

Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm 

Hood Condition

Hood



Running Board Condition

Left Running Board



Right Running Board



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Boot Floor



Head Light Support Condition



Cowl Top

Cowl Top



Panel Condition

Rear Trunk Panel	✓		
------------------	---	--	--

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
-------------	---	--------------------	---

Engine Oil (Condition & Level)	✓	Radiator Condition	✓
--------------------------------	---	--------------------	---

Radiator Coolant	✓		
------------------	---	--	--

Transmission Operation

Gear Shifting	✓	Drive Axle	✓
---------------	---	------------	---

Steering, Suspension & Brakes

Brake System

Parking Brake	✓	Brake Master Cylinder	✓
---------------	---	-----------------------	---

Suspension

Shock Absorbers	✓		
-----------------	---	--	--

Electricals, Controls & Lights

Keys

Master Key	✓		
------------	---	--	--

Dashboard

Instrument Panel	✓		
------------------	---	--	--

Controls	✓	Infotainment Display	✓
----------	---	----------------------	---

Music System	✓		
--------------	---	--	--

Lights

Headlight	✓	Tail Light Cluster	✓
-----------	---	--------------------	---

Daylight Running Lights	✓		
-------------------------	---	--	--

Air Conditioning

AC Cooling	✓		
------------	---	--	--

Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Steering Wheel



Headliner



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<35%

LHS Rear Tyre

<35%

RHS Front Tyre

<35%

RHS Rear Tyre

<35%

Spare Tyre

<15%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE