



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



COMING SOON



2025 MITSUBISHI OUTLANDER

MIDLINE | 52,227 KM

VIN: JE4M3W184SZ704318

## Car highlights



### Cruise control

Cruise control to drive with ease & comfort



### Great Parking Assistance

Parking Sensors Front, Reverse Camera & more

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable



### Apple play

Enjoy your drive with apple play



### Amazing Comfort

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 52227             |  Specs             | Yes                  |
|  Engine           | 2.5L              |  Option Type       | Semi Loaded          |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SUV               |  Fuel              | Petrol               |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 6 Airbags            |
|  Seating Capacity | 7 Seats           |  Number of keys    | 1 Keys               |
|  VIN number      | JE4M3W184SZ704318 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                     |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                     |                                                                                       |
| Climate Control AC                                                                                                   |  | Cruise Control                      |  |
| Power Window front - Drivers Side                                                                                    |  | Power Window front - Passenger Side |  |
| Power Windows Rear                                                                                                   |  |                                     |                                                                                       |
|  <b>Exteriors</b>                 |                                                                                     |                                     |                                                                                       |
| Fog Light Front                                                                                                      |  | Roof Rails                          |  |

|                                                                                                                |   |                      |   |
|----------------------------------------------------------------------------------------------------------------|---|----------------------|---|
| Running Lights                                                                                                 | ✓ | Rear Bumper Spoiler  | ✓ |
|  <b>Performance</b>           |   |                      |   |
| Paddle Shift                                                                                                   | ✓ | Hill Descent Control | ✓ |
|  <b>Safety &amp; Security</b> |   |                      |   |
| Parking Sensors Front                                                                                          | ✓ | Parking Sensors Rear | ✓ |
| Reverse Camera                                                                                                 | ✓ | Airbag Sides         | ✓ |
| Airbag Curtain Shield                                                                                          | ✓ | Airbag Driver Front  | ✓ |
| Airbag Passenger Front                                                                                         | ✓ | ABS                  | ✓ |
|  <b>Entertainment</b>         |   |                      |   |
| Bluetooth Player                                                                                               | ✓ | Apple Play           | ✓ |
| Android Auto Play                                                                                              | ✓ |                      |   |

## 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



### Exterior

#### Doors condition

Front right door

Panel: Paint Defect



Rear left door

Panel: Paint Chip-off



Rear right door

Panel: Paint Defect, Dent > 30mm



#### Fenders Condition

Left Fender



Right Fender



#### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: VIP Tag/ other sticker



#### Rear Bumper Condition

Rear Bumper

Rear Bumper: Scuffing > 80mm, Dent > 50mm



#### Hood Condition

Hood



#### Roof Condition

Roof



#### Running Board Condition

Left Running Board



Right Running Board



#### Windshield Condition

Front Windshield

Condition: Front Wiper blades need replacement



Rear Windshield

Wiper blade damaged



#### Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



|                                    |   |                                     |   |
|------------------------------------|---|-------------------------------------|---|
| Head Light Support Condition       | ✓ |                                     |   |
| Cowl Top                           |   |                                     |   |
| Cowl Top                           | ✓ |                                     |   |
| Rear View Mirror Condition         |   |                                     |   |
| Left Hand Side Mirror              | ✓ | Right Side Mirror<br>Body: Scuffing | ! |
| Alloy Wheel/ Rim                   |   |                                     |   |
| Left Front Alloy/ Rim              | ✓ | Left Rear Alloy/ Rim                | ✓ |
| Right Front Alloy/ Rim             | ✓ | Right Rear Alloy/ Rim               | ✓ |
| Grill Condition<br>Scuffing > 50mm | ! | Monogram                            | ✓ |
| Panel Condition                    |   |                                     |   |
| Rear Trunk Panel                   | ✓ |                                     |   |

## Engine & Transmission

|                        |   |                                |   |
|------------------------|---|--------------------------------|---|
| Engine                 |   |                                |   |
| Engine Performance     | ✓ | Engine Oil (Condition & Level) | ✓ |
| Exhaust System         | ✓ | Radiator Condition             | ✓ |
| Radiator Coolant       | ✓ |                                |   |
| Transmission Operation |   |                                |   |
| Gear Shifting          | ✓ | Drive Axle                     | ✓ |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

|            |   |
|------------|---|
| Keys       |   |
| Master Key | ✓ |

|                                          |   |                         |   |
|------------------------------------------|---|-------------------------|---|
| Dashboard                                |   |                         |   |
| Instrument Panel                         | ✓ |                         |   |
| Controls                                 | ✓ | Cruise Control          | ✓ |
| Infotainment Display                     | ✓ | Music System            | ✓ |
| Camera                                   | ✓ |                         |   |
| Lights                                   |   |                         |   |
| Headlight                                | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster                       | ✓ | Daylight Running Lights | ✓ |
| Fog Lights                               | ✓ |                         |   |
| Air Conditioning                         |   |                         |   |
| AC Cooling                               | ! | AC System Leaks         | ✓ |
| AC Temperature: Ac vents broken/ damaged |   |                         |   |
| Rear Blower Switch                       | ✓ |                         |   |
| Power/ Manual Windows                    | ✓ |                         |   |

## Interiors & Luggage

|                                                           |   |                                            |   |
|-----------------------------------------------------------|---|--------------------------------------------|---|
| Dashboard And Instrument Panel                            |   | Central Console                            |   |
| Dashboard Upholstery: Scuffing/Crack/ Fair Use Wear> 10mm | ! | Gear Shift Knob: Knob Fair Use Wear        | ! |
| Cup Holder                                                | ✓ | Steering Wheel                             | ! |
|                                                           |   | Color Faded                                |   |
| Sunvisor                                                  | ✓ | Seat Upholstery                            | ✓ |
| Manual Seat Movement                                      | ✓ | Seat Belts                                 | ! |
|                                                           |   | Rear Center Seat Belt: Crack/Fair Use Wear |   |
| Head Rest                                                 | ✓ | Door Controls And Trim                     | ✓ |
| Carpet                                                    | ! | Headliner                                  | ✓ |
| Front Left Floor Mat: Smudge/Burn/Crack                   |   |                                            |   |
| Rear View Mirror                                          | ! | Toolkit                                    | ✓ |
| Damaged Mirror Casing                                     |   |                                            |   |

## Tyres

### Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



### Life remaining

LHS Front Tyre

<85%

LHS Rear Tyre

<85%

RHS Front Tyre

<85%

RHS Rear Tyre

<85%

Spare Tyre

<65%



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE