



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2025 MITSUBISHI OUTLANDER

MIDLINE | 11,730 KM

VIN: JE4M3W187SZ709027

Car highlights



Great condition

Car has low imperfections



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	11730	 Specs	Yes
 Engine	2.5L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	7 Seats	 Number of keys	1 Keys
 VIN number	JE4M3W187SZ709027		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Power Window front - Drivers Side	
Power Window front - Passenger Side		Power Windows Rear	
 Safety & Security			
Parking Sensors Rear		Airbag Driver Front	
Airbag Passenger Front		ABS	



Exteriors

Roof Rails



Running Lights



Rear Bumper Spoiler



Entertainment

Bluetooth Player



Apple Play



Android Auto Play



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Roof Condition

Roof



Running Board Condition

Left Running Board



Right Running Board



Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top		
Cowl Top	✓	
Rear View Mirror Condition		
Left Hand Side Mirror	✓	Right Side Mirror ✓
Alloy Wheel/ Rim		
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim ✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim ✓
Monogram	✓	
Panel Condition		
Rear Trunk Panel	✓	

Engine & Transmission

Engine		
Engine Body	✓	Engine Performance ✓
Engine Oil (Condition & Level)	✓	Exhaust System ✓
Turbocharger/ Supercharger	✓	Radiator Condition ✓
Radiator Coolant	✓	
Transmission Operation		
Gear Shifting	✓	Drive Axle ✓

Steering, Suspension & Brakes

Steering		
Steering wheel	✓	
Brake System		
Parking Brake	✓	Brake Master Cylinder ✓
Brake Fluid	✓	
Suspension		
Shock Absorbers	✓	

Electricals, Controls & Lights

Keys			
Master Key	✓		
Dashboard			
Instrument Panel	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Music System	✓
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
Air Conditioning			
AC Cooling	✓	AC System Leaks	✓
Rear Blower Switch	✓	Rear Left AC Vent	✓
Rear Entertainment	✓	Power/ Manual Windows	✓
Memory Seats	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Steering Wheel	✓
Sunvisor	✓	Seat Upholstery	✓
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

 Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre





A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE