



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



COMING SOON



2020 MITSUBISHI PAJERO

GLS HIGHLINE | 97,635 KM

VIN: JE4NR62R3LJ710251

Car highlights



Four wheel drive

This car has a Four wheel drive



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	97635	 Specs	Yes
 Engine	3.8L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	Fuel Efficiency	8.45 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	JE4NR62R3LJ710251		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Power Window front - Drivers Side		Power Window front - Passenger Side	
Power Windows Rear			
 Exteriors			
Fog Light Front		Roof Rails	

Running Lights	✓	Rear Bumper Spoiler	✓
 Safety & Security			
Parking Sensors Rear	✓	Reverse Camera	✓
Blind Spot Monitor	✓	Airbag Sides	✓
Airbag Curtain Shield	✓	Airbag Driver Front	✓
Airbag Passenger Front	✓	ABS	✓
 Performance			
Differential Locks	✓		
 Entertainment			
Bluetooth Player	✓		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door

Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm 

Rear left door 

Rear right door

Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm 

Fenders Condition

Left Fender

Condition: Light Scuffing, Fender liner missing/ damaged/ misaligned, Wheel arch rusted/ cracked / dirty 

Right Fender
Right Fender: Paint Chip-off 

Quarter Panels Condition

Left Quarter Panel 

Right Quarter Panel
Condition: Light Scuffing 

Rear Bumper Condition

Rear Bumper

Rear Bumper: Scuffing > 80mm, Crack/ Misaligned 

Hood Condition

Hood

Bonnet: Light Scuffing < 50mm 

Roof Condition

Roof 

Running Board Condition

Left Running Board

Condition: Fair Use Wear 

Right Running Board

Condition: Fair Use Wear 

Windshield Condition

Front Windshield

Condition: Front Wiper blades need replacement 

Rear Windshield

Wiper blade damaged 

Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top

Cowl Top

Fair Use Wear/Crack<5mm



Rear View Mirror Condition

Left Hand Side Mirror



Right Side Mirror



Alloy Wheel/ Rim

Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Grill Condition

Scuffing > 50mm



Monogram



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Transmission Operation

Gear Shifting



Drive Axle



4*4 Condition (If Applicable)



Steering, Suspension & Brakes

Brake System

Parking Brake



Brake Master Cylinder



Brake Fluid

Front Brake Discs Thickness < Manufacturer
Standard



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Dashboard

Instrument Panel



Controls



Cruise Control



Infotainment Display



Music System



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



Daylight Running Lights



Fog Lights



Air Conditioning

AC Cooling



AC System Leaks



Rear Blower Switch



Rear Left AC Vent
RHS Crack/Fair Use Wear



Rear Entertainment

Left Seat LCD: Damaged



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/
Disfiguration/ Melted



Central Console

Gear Shift Knob: Knob Fair Use Wear



Cup Holder



Steering Wheel

Color Faded



Sunvisor



Seat Upholstery

Rear Left Seat: Minor Smudge/ Crack, Minor
Leather/ Fabric Fair Use Wear/ Tears



Manual Seat Movement

Passenger Seat: Adjuster Switch
Damage/Missing



Seat Belts



Head Rest



Door Controls And Trim



Carpet

Front Left Floor Mat: Smudge/Burn/Crack



Headliner



Rear View Mirror

Damaged Mirror Casing



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<75%

LHS Rear Tyre

<65%

RHS Front Tyre

<75%

RHS Rear Tyre

<65%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE