



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

12 Months Warranty

This car comes with 12 months or 20,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 BMW 440i

M SPORT | 111,320 KM

VIN: WBA4J5A0XKBN80016

Car highlights

Service History

Service history available



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat, Memory Seats

Basic Details

 Kilometers	111320	 Specs	Yes
 Engine	3.0L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Rear Wheel Drive
 Body Type	COUPE	Fuel Efficiency	12.3 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	WBA4J5A0XKBN80016		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
360 degree Camera		Navigation	
Parking Sensors Front		Parking Sensors Rear	
Reverse Camera		Blind Spot Monitor	
Front Camera		Side Camera	
Airbag Sides		Airbag Curtain Shield	

Airbag Driver Front	✓	Airbag Passenger Front	✓
ABS	✓		
 Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Memory Seats	✓	Power Window front - Drivers Side	✓
Power Window front - Passenger Side	✓	Power Tailgate/ Power Trunk	✓
Power Windows Rear	✓		
 Performance			
Paddle Shift	✓		
 Exteriors			
Running Lights	✓		
 Entertainment			
Bluetooth Player	✓		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door Panel: Dent > 30mm		Rear left door Panel: Dent	
--	---	-------------------------------	---

Rear right door Panel: Low Visual Dent < 30mm	
--	---

Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---

Quarter Panels Condition

Left Quarter Panel Condition: Dent		Right Quarter Panel	
---------------------------------------	---	---------------------	---

Rear Bumper Condition

Rear Bumper	
-------------	---

Hood Condition

Hood	
------	---

Running Board Condition

Left Running Board		Right Running Board	
--------------------	---	---------------------	---

Sunroof Glass Condition (If Equipped)

Sun Roof Glass	
----------------	---

Windshield Condition

Front Windshield		Rear Windshield	
------------------	---	-----------------	---

Structural Assessment

Chassis Condition		Boot Floor	
-------------------	---	------------	---

Head Light Support Condition	
------------------------------	---

Cowl Top

Cowl Top Fair Use Wear/Crack>5mm	
-------------------------------------	---

Alloy Wheel/ Rim		
Left Rear Alloy/ Rim	⚠	Right Front Alloy/ Rim
Rim: Alloy Edge Scuffing		Rim: Alloy Edge Scuffing
Right Rear Alloy/ Rim	✓	
Panel Condition		
Rear Trunk Panel	✓	

🔧 Engine & Transmission

Engine		
Engine Body	✓	Engine Performance
Engine Oil (Condition & Level)	✓	Turbocharger/ Supercharger
Radiator Condition	✓	Radiator Coolant
Transmission Operation		
Gear Shifting	✓	Drive Axle

🚗 Steering, Suspension & Brakes

Brake System		
Parking Brake	✓	Brake Master Cylinder
Suspension		
Shock Absorbers	✓	

🔌 Electricals, Controls & Lights

Keys		
Master Key	✓	
Dashboard		
Instrument Panel	✓	
Controls	✓	Infotainment Display
Music System	✓	Camera
		Reverse Camera: Lens Damaged/ Blurred
Lights		
Headlight	⚠	Tail Light Cluster
Left: Low Brightness lamps		✓

Daylight Running Lights



Air Conditioning

AC Cooling



Power/ Manual Windows



Memory Seats



Interiors & Luggage

Dashboard And Instrument Panel



Steering Wheel



Headliner



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Life remaining

LHS Front Tyre

<90%

LHS Rear Tyre

<90%

RHS Front Tyre

<90%

RHS Rear Tyre

<90%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE