



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



COMING SOON



2024 TOYOTA CAMRY

SE | 84,146 KM

VIN: JTNB14HK1R3232343

## Car highlights



### Sunroof

This car has a sunroof



### Cruise control

Cruise control to drive with ease & comfort

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K  
applicable



### Apple play

Enjoy your drive with apple play



### Amazing Comfort

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 84146             |  Specs             | Yes                  |
|  Engine           | 2.5L              |  Option Type       | Semi Loaded          |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SEDAN             | Fuel Efficiency                                                                                     | 12.2 km/L mileage    |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 8 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys               |
|  VIN number     | JTNB14HK1R3232343 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                     |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                     |                                                                                       |
| Climate Control AC                                                                                                   |  | Cruise Control                      |  |
| Power Window front - Drivers Side                                                                                    |  | Power Window front - Passenger Side |  |
| Power Windows Rear                                                                                                   |  |                                     |                                                                                       |
|  <b>Exteriors</b>                 |                                                                                     |                                     |                                                                                       |
| Fog Light Front                                                                                                      |  | Running Lights                      |  |



## Safety & Security

Parking Sensors Rear



Reverse Camera



Airbag Sides



Airbag Curtain Shield



Airbag Driver Front



Airbag Passenger Front



ABS



## Entertainment

Bluetooth Player



Apple Play



Android Auto Play



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front right door



Rear left door



Rear right door

Panel: Low Visual Dent < 30mm, Paint Chip-off < 5mm



### Fenders Condition

Left Fender



Right Fender



### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



### Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



### Hood Condition

Hood



### Roof Condition

Roof



### Running Board Condition

Left Running Board



Right Running Board



### Sunroof Glass Condition (If Equipped)

Sun Roof Glass

Noise/Vibration



### Windshield Condition

Front Windshield

Condition: Front Wiper blades need replacement



Rear Windshield



### Structural Assessment

|                              |   |                       |   |
|------------------------------|---|-----------------------|---|
| Chassis Condition            | ✓ | Apron                 | ✓ |
| Boot Floor                   | ✓ | Firewall Condition    | ✓ |
| Head Light Support Condition | ✓ |                       |   |
| Cowl Top                     |   |                       |   |
| Cowl Top                     | ✓ |                       |   |
| Rear View Mirror Condition   |   |                       |   |
| Left Hand Side Mirror        | ✓ | Right Side Mirror     | ✓ |
| Alloy Wheel/ Rim             |   |                       |   |
| Left Front Alloy/ Rim        | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim       | ✓ | Right Rear Alloy/ Rim | ✓ |
| Monogram                     | ✓ |                       |   |
| Panel Condition              |   |                       |   |
| Rear Trunk Panel             | ✓ |                       |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid     | ✓ |                       |   |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

|                       |   |                         |   |
|-----------------------|---|-------------------------|---|
| Keys                  |   |                         |   |
| Master Key            | ✓ |                         |   |
| Dashboard             |   |                         |   |
| Instrument Panel      | ✓ |                         |   |
| Controls              | ✓ | Cruise Control          | ✓ |
| Infotainment Display  | ✓ | Music System            | ✓ |
| Camera                | ✓ |                         |   |
| Lights                |   |                         |   |
| Headlight             | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster    | ✓ | Daylight Running Lights | ✓ |
| Fog Lights            | ✓ |                         |   |
| Air Conditioning      |   |                         |   |
| AC Cooling            | ✓ | AC System Leaks         | ✓ |
| Rear Blower Switch    | ✓ |                         |   |
| Power/ Manual Windows | ✓ |                         |   |

## Interiors & Luggage

|                                         |   |                              |   |
|-----------------------------------------|---|------------------------------|---|
| Dashboard And Instrument Panel          | ✓ | Central Console              | ✓ |
| Cup Holder                              | ✓ | Steering Wheel               | ! |
|                                         |   | Steering Wheel Fair Use Wear |   |
| Sunvisor                                | ✓ | Seat Upholstery              | ✓ |
| Manual Seat Movement                    | ✓ | Seat Belts                   | ✓ |
| Head Rest                               | ✓ | Door Controls And Trim       | ✓ |
| Carpet                                  |   | Headliner                    | ✓ |
| Front Left Floor Mat: Smudge/Burn/Crack | ! |                              |   |
| Rear View Mirror                        |   | Toolkit                      | ✓ |
| Mirror Assembly Loose                   | ! |                              |   |

## Tyres

### Tyres Condition

Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



### Life remaining

LHS Front Tyre

<65%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

<65%



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE