



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2025 JETOUR X 70 PLUS**

**LUXURY | 34,209 KM**

VIN: LVTDB21B3SD604577

## Car highlights



### **Panoramic Roof**

This car has a panoramic roof



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Music System**

Enjoy your drive with music system



### **Amazing Comfort**

Power driver seat, Memory Seats & more

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 34209             |  Specs             | Yes                  |
|  Engine           | 1.6L              |  Option Type       | Fully Loaded         |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SUV               |  Fuel              | Petrol               |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 6 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys               |
|  VIN number     | LVTDB21B3SD604577 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                       |                                                                                     |                       |                                                                                       |
|-------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------|---------------------------------------------------------------------------------------|
|  Safety & Security |                                                                                     |                       |                                                                                       |
| 360 degree Camera                                                                                     |  | Parking Sensors Front |  |
| Parking Sensors Rear                                                                                  |  | Blind Spot Monitor    |  |
| Collision Warning System                                                                              |  | Airbag Sides          |  |
| Airbag Curtain Shield                                                                                 |  | Airbag Driver Front   |  |
| Airbag Passenger Front                                                                                |  | ABS                   |  |



### Comfort & Convenience

Climate Control AC



Cruise Control



Memory Seats



Power Window front -  
Drivers Side



Power Window front -  
Passenger Side



Ventilated Seat



Power Tailgate/ Power  
Trunk



Power Windows Rear



### Exteriors

Fog Light Front



Running Lights



### Performance

Paddle Shift



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                  |                                                                                   |                |                                                                                     |
|------------------|-----------------------------------------------------------------------------------|----------------|-------------------------------------------------------------------------------------|
| Front right door |  | Rear left door |  |
|------------------|-----------------------------------------------------------------------------------|----------------|-------------------------------------------------------------------------------------|

|                                     |                                                                                   |
|-------------------------------------|-----------------------------------------------------------------------------------|
| Rear right door                     |  |
| Panel: Dent > 30mm, Scuffing > 50mm |                                                                                   |

### Fenders Condition

|             |                                                                                   |              |                                                                                     |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|
| Left Fender |  | Right Fender |  |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|

### Quarter Panels Condition

|                    |                                                                                   |                              |                                                                                     |
|--------------------|-----------------------------------------------------------------------------------|------------------------------|-------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel          |  |
|                    |                                                                                   | Condition: Scuffing/ Scratch |                                                                                     |

### Rear Bumper Condition

|                              |                                                                                     |
|------------------------------|-------------------------------------------------------------------------------------|
| Rear Bumper                  |  |
| Rear Bumper: Scuffing > 80mm |                                                                                     |

### Hood Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Hood |  |
|------|-------------------------------------------------------------------------------------|

### Running Board Condition

|                    |                                                                                     |                     |                                                                                       |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|
| Left Running Board |  | Right Running Board |  |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|

### Sunroof Glass Condition (If Equipped)

|                |                                                                                     |
|----------------|-------------------------------------------------------------------------------------|
| Sun Roof Glass |  |
|----------------|-------------------------------------------------------------------------------------|

### Windshield Condition

|                                 |                                                                                     |                 |                                                                                       |
|---------------------------------|-------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------------------------------|
| Front Windshield                |  | Rear Windshield |  |
| Condition: Driver Side/Scuffing |                                                                                     |                 |                                                                                       |

### Structural Assessment

|                   |                                                                                     |            |                                                                                       |
|-------------------|-------------------------------------------------------------------------------------|------------|---------------------------------------------------------------------------------------|
| Chassis Condition |  | Boot Floor |  |
|-------------------|-------------------------------------------------------------------------------------|------------|---------------------------------------------------------------------------------------|

|                              |                                                                                     |
|------------------------------|-------------------------------------------------------------------------------------|
| Head Light Support Condition |  |
|------------------------------|-------------------------------------------------------------------------------------|

### Cowl Top

|          |                                                                                     |
|----------|-------------------------------------------------------------------------------------|
| Cowl Top |  |
|----------|-------------------------------------------------------------------------------------|

|                        |   |                         |
|------------------------|---|-------------------------|
| Alloy Wheel/ Rim       |   |                         |
| Left Front Alloy/ Rim  | ✓ | Left Rear Alloy/ Rim ✓  |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim ✓ |
| Panel Condition        |   |                         |
| Rear Trunk Panel       | ✓ |                         |

## Engine & Transmission

|                                |   |                              |
|--------------------------------|---|------------------------------|
| Engine                         |   |                              |
| Engine Body                    | ✓ | Engine Performance ✓         |
| Engine Oil (Condition & Level) | ✓ | Turbocharger/ Supercharger ✓ |
| Radiator Condition             | ✓ | Radiator Coolant ✓           |
| Transmission Operation         |   |                              |
| Gear Shifting                  | ✓ | Drive Axle ✓                 |

## Steering, Suspension & Brakes

|                 |   |                         |
|-----------------|---|-------------------------|
| Brake System    |   |                         |
| Parking Brake   | ✓ | Brake Master Cylinder ✓ |
| Suspension      |   |                         |
| Shock Absorbers | ✓ |                         |

## Electricals, Controls & Lights

|                         |   |                        |
|-------------------------|---|------------------------|
| Keys                    |   |                        |
| Master Key              | ✓ |                        |
| Dashboard               |   |                        |
| Instrument Panel        | ✓ |                        |
| Controls                | ✓ | Infotainment Display ✓ |
| Music System            | ✓ | Camera ✓               |
| Lights                  |   |                        |
| Headlight               | ✓ | Tail Light Cluster ✓   |
| Daylight Running Lights | ✓ |                        |

Air Conditioning

AC Cooling



Power/ Manual Windows



Memory Seats



## Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Steering Wheel



Headliner



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<73%

LHS Rear Tyre

<73%

RHS Front Tyre

<73%

RHS Rear Tyre

<73%

Spare Tyre

<55%



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE