



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2024 MG GT

STD | 45,132 KM

VIN: LSJA36U37RN014043

## Car highlights



### **Great condition**

Car has low imperfections



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Apple play**

Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat

## Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 45132             |  Specs             | Yes                  |
|  Engine           | 1.5L              |  Option Type       | Basic                |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SEDAN             |  Fuel              | Petrol               |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Brown |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys               |
|  VIN number       | LSJA36U37RN014043 |                                                                                                     |                      |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                   |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                   |                                                                                       |
| Cruise Control                                                                                                       |  | Power Window front - Drivers Side |  |
| Power Window front - Passenger Side                                                                                  |  | Power Windows Rear                |  |
|  <b>Safety &amp; Security</b>     |                                                                                     |                                   |                                                                                       |
| Parking Sensors Rear                                                                                                 |  | Reverse Camera                    |  |
| Airbag Driver Front                                                                                                  |  | Airbag Passenger Front            |  |

|                                                                                                        |   |              |
|--------------------------------------------------------------------------------------------------------|---|--------------|
| ABS                                                                                                    | ✓ |              |
|  <b>Exteriors</b>     |   |              |
| Running Lights                                                                                         | ✓ |              |
|  <b>Entertainment</b> |   |              |
| Bluetooth Player                                                                                       | ✓ | Apple Play ✓ |
| Android Auto Play                                                                                      | ✓ |              |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

|                              |                                                                                     |                     |                                                                                       |
|------------------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|
| Doors condition              |                                                                                     |                     |                                                                                       |
| Front right door             |    | Rear left door      |    |
| Rear right door              |    |                     |                                                                                       |
| Panel: Dent > 30mm           |                                                                                     |                     |                                                                                       |
| Fenders Condition            |                                                                                     |                     |                                                                                       |
| Left Fender                  |    | Right Fender        |    |
| Quarter Panels Condition     |                                                                                     |                     |                                                                                       |
| Left Quarter Panel           |    | Right Quarter Panel |    |
| Rear Bumper Condition        |                                                                                     |                     |                                                                                       |
| Rear Bumper                  |  |                     |                                                                                       |
| Rear Bumper: Fully Repainted |                                                                                     |                     |                                                                                       |
| Hood Condition               |                                                                                     |                     |                                                                                       |
| Hood                         |  |                     |                                                                                       |
| Roof Condition               |                                                                                     |                     |                                                                                       |
| Roof                         |  |                     |                                                                                       |
| Running Board Condition      |                                                                                     |                     |                                                                                       |
| Left Running Board           |  | Right Running Board |  |
| Windshield Condition         |                                                                                     |                     |                                                                                       |
| Front Windshield             |  | Rear Windshield     |  |
| Structural Assessment        |                                                                                     |                     |                                                                                       |
| Chassis Condition            |  | Apron               |  |
| Boot Floor                   |  | Firewall Condition  |  |
| Head Light Support Condition |  |                     |                                                                                       |
| Cowl Top                     |                                                                                     |                     |                                                                                       |

|                            |   |                       |   |
|----------------------------|---|-----------------------|---|
| Cowl Top                   | ✓ |                       |   |
| Rear View Mirror Condition |   |                       |   |
| Left Hand Side Mirror      | ✓ | Right Side Mirror     | ✓ |
| Alloy Wheel/ Rim           |   |                       |   |
| Left Front Alloy/ Rim      | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim     | ✓ | Right Rear Alloy/ Rim | ✓ |
| Grill Condition            | ! | Monogram              | ✓ |
| Fully Repainted            |   |                       |   |
| Panel Condition            |   |                       |   |
| Rear Trunk Panel           | ✓ |                       |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid     | ✓ |                       |   |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

|                  |   |
|------------------|---|
| Keys             |   |
| Master Key       | ✓ |
| Dashboard        |   |
| Instrument Panel | ✓ |

|                      |   |                         |   |
|----------------------|---|-------------------------|---|
| Controls             | ✓ | Cruise Control          | ✓ |
| Infotainment Display | ✓ | Music System            | ✓ |
| Camera               | ✓ |                         |   |
| Lights               |   |                         |   |
| Headlight            | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster   | ✓ | Daylight Running Lights | ✓ |
| Air Conditioning     |   |                         |   |
| AC Cooling           | ✓ | AC System Leaks         | ✓ |
| Rear Blower Switch   | ✓ | Rear Left AC Vent       | ✓ |
| Rear Entertainment   | ✓ | Power/ Manual Windows   | ✓ |



## Interiors & Luggage

|                                |   |                        |   |
|--------------------------------|---|------------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console        | ✓ |
| Cup Holder                     | ✓ | Steering Wheel         | ✓ |
| Sunvisor                       | ✓ | Seat Upholstery        | ✓ |
| Manual Seat Movement           | ✓ | Seat Belts             | ✓ |
| Head Rest                      | ✓ | Door Controls And Trim | ✓ |
| Carpet                         | ✓ | Headliner              | ✓ |
| Rear View Mirror               | ✓ | Toolkit                | ✓ |



## Tyres

|                            |   |                           |   |
|----------------------------|---|---------------------------|---|
| Tyres Condition            |   |                           |   |
| Left Hand Side Front Tyre  | ✓ | Left Hand Side Rear Tyre  | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre                 | ✓ |                           |   |
| Life remaining             |   |                           |   |

|                |      |               |      |
|----------------|------|---------------|------|
| LHS Front Tyre | <55% | LHS Rear Tyre | <55% |
| RHS Front Tyre | <55% | RHS Rear Tyre | <55% |
| Spare Tyre     | <55% |               |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE