



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2019 MITSUBISHI ASX**

**GLX | 94,979 KM**

VIN: JE4LP21U6KU700712

### **Car highlights**



#### **Cruise control**

Cruise control to drive with ease & comfort



#### **Great Parking Assistance**

Reverse Camera



#### **Music System**

Enjoy your drive with music system



#### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 94979             |  Specs             | Yes                  |
|  Engine           | 2.0L              |  Option Type       | Basic                |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SUV               | Fuel Efficiency                                                                                     | 12.5 km/L mileage    |
|  Wheel Type       | Steel Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys               |
|  VIN number     | JE4LP21U6KU700712 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                   |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                   |                                                                                       |
| Cruise Control                                                                                                       |  | Power Window front - Drivers Side |  |
| Power Window front - Passenger Side                                                                                  |  | Power Windows Rear                |  |
|  <b>Safety &amp; Security</b>     |                                                                                     |                                   |                                                                                       |
| Reverse Camera                                                                                                       |  | Airbag Driver Front               |  |
| Airbag Passenger Front                                                                                               |  | ABS                               |  |



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front right door

Panel: Paint Chip-off > 5mm



Rear left door

Panel: Scuffing, Paint Chip-off



Rear right door

Panel: Light Scuffing < 50mm, Paint Chip-off > 5mm



### Fenders Condition

Left Fender

Condition: Paint Chip-off



Right Fender



### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Chip



### Rear Bumper Condition

Rear Bumper

Rear Bumper: Fully Repainted, Scuffing > 80mm, Chip> 8mm



### Hood Condition

Hood



### Running Board Condition

Left Running Board



Right Running Board



### Windshield Condition

Front Windshield



Rear Windshield



### Structural Assessment

Chassis Condition



Boot Floor



Head Light Support Condition



Cowl Top

Cowl Top



|                        |   |                         |
|------------------------|---|-------------------------|
| Alloy Wheel/ Rim       |   |                         |
| Left Front Alloy/ Rim  | ✓ | Left Rear Alloy/ Rim ✓  |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim ✓ |
| Grill Condition        | ! |                         |
| Fully Repainted        |   |                         |
| Panel Condition        |   |                         |
| Rear Trunk Panel       | ✓ |                         |

## Engine & Transmission

|                                |   |                      |
|--------------------------------|---|----------------------|
| Engine                         |   |                      |
| Engine Body                    | ✓ | Engine Performance ✓ |
| Engine Oil (Condition & Level) | ✓ | Radiator Condition ✓ |
| Radiator Coolant               | ✓ |                      |
| Transmission Operation         |   |                      |
| Gear Shifting                  | ✓ | Drive Axle ✓         |

## Steering, Suspension & Brakes

|                 |   |                         |
|-----------------|---|-------------------------|
| Brake System    |   |                         |
| Parking Brake   | ✓ | Brake Master Cylinder ✓ |
| Suspension      |   |                         |
| Shock Absorbers | ✓ |                         |

## Electricals, Controls & Lights

|                  |   |                        |
|------------------|---|------------------------|
| Keys             |   |                        |
| Master Key       | ✓ |                        |
| Dashboard        |   |                        |
| Instrument Panel | ✓ |                        |
| Controls         | ✓ | Infotainment Display ✓ |
| Music System     | ✓ | Camera ✓               |
| Lights           |   |                        |

|                         |   |                    |   |
|-------------------------|---|--------------------|---|
| Headlight               | ✓ | Tail Light Cluster | ✓ |
| Daylight Running Lights | ✓ |                    |   |
| Air Conditioning        |   |                    |   |
| AC Cooling              | ✓ |                    |   |
| Power/ Manual Windows   | ✓ |                    |   |

## Interiors & Luggage

|                                |   |                |   |
|--------------------------------|---|----------------|---|
| Dashboard And Instrument Panel | ✓ | Steering Wheel | ✓ |
| Headliner                      | ✓ |                |   |

## Tyres

|                           |      |                            |      |
|---------------------------|------|----------------------------|------|
| Tyres Condition           |      |                            |      |
| Left Hand Side Rear Tyre  | ✓    | Right Hand Side Front Tyre | ✓    |
| Right Hand Side Rear Tyre | ✓    | Spare Tyre                 | ✓    |
| Life remaining            |      |                            |      |
| LHS Front Tyre            | <90% | LHS Rear Tyre              | <90% |
| RHS Front Tyre            | <90% | RHS Rear Tyre              | <90% |
| Spare Tyre                | <65% |                            |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE