



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 MITSUBISHI MONTERO SPORT

GLX M/L SIGNATURE EDITION | 54,181 KM

VIN: MMEMC71X4KH008875

Car highlights



Four wheel drive

This car has a Four wheel drive



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	54181	 Specs	Yes
 Engine	3.0L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Brown
 Interior Trim	Leather Trim	 Number of Airbags	2 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	MMEMC71X4KH008875		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Power Window front - Drivers Side		Power Window front - Passenger Side	
Power Windows Rear			
 Exteriors			
Fog Light Front		Running Lights	

Rear Bumper Spoiler	✓	
 Performance		
Paddle Shift	✓	Hill Descent Control ✓
 Safety & Security		
Parking Sensors Front	✓	Parking Sensors Rear ✓
Reverse Camera	✓	Airbag Driver Front ✓
Airbag Passenger Front	✓	ABS ✓
 Entertainment		
Rear Seat Entertainment	✓	Bluetooth Player ✓

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front right door

Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm



Rear left door



Rear right door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm



Fenders Condition

Left Fender



Right Fender

Right Fender: Scuffing



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Low Visual Dent



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Acid Marks/ Bird Dropping < 5mm



Roof Condition

Roof



Running Board Condition

Left Running Board



Right Running Board



Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield

Condition: Front Wiper blades need



Rear Windshield



replacement			
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Right Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Monogram			
Missing monogram/ logo	!		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓

Brake Fluid	✓	
Suspension		
Shock Absorbers	✓	

📅 Electricals, Controls & Lights

Keys		
Master Key	✓	
Dashboard		
Instrument Panel	✓	
Controls	✓	Cruise Control ✓
Infotainment Display	✓	Music System ✓
Camera	✓	
Lights		
Headlight		
Right: Scuff Marks > 50mm, Low Brightness Lamps	⚠	Interior Lights ✓
Tail Light Cluster	✓	Daylight Running Lights ✓
Fog Lights	✓	
Air Conditioning		
AC Cooling	✓	AC System Leaks ✓
Rear Blower Switch	✓	Rear Left AC Vent ⚠ RHS Crack/Fair Use Wear
Rear Entertainment	✓	Power/ Manual Windows ⚠ Front Left: Master Switch Buttons Faded

🧳 Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console ✓
Cup Holder	✓	Steering Wheel ⚠ Steering Wheel Fair Use Wear
Sunvisor	✓	Seat Upholstery ✓

Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			
LHS Front Tyre	<75%	LHS Rear Tyre	<85%
RHS Front Tyre	<75%	RHS Rear Tyre	<85%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE