



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2024 MITSUBISHI ASX**

**PRIME EDITION | 75,016 KM**

VIN: JE4LPT1U3RU702997

## **Car highlights**



### **Good Tyre Condition**

Tyre age less than 2 years



### **Cruise control**

Cruise control to drive with ease & comfort



### **Apple play**

Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 75016             |  Specs             | Yes                  |
|  Engine           | 2.0L              |  Option Type       | Fully Loaded         |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SUV               |  Fuel              | Petrol               |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 2 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys               |
|  VIN number      | JE4LPT1U3RU702997 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                     |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                     |                                                                                       |
| Climate Control AC                                                                                                   |  | Cruise Control                      |  |
| Power Window front - Drivers Side                                                                                    |  | Power Window front - Passenger Side |  |
| Power Windows Rear                                                                                                   |  |                                     |                                                                                       |
|  <b>Safety &amp; Security</b>     |                                                                                     |                                     |                                                                                       |
| Parking Sensors Rear                                                                                                 |  | Reverse Camera                      |  |

|                                                                                                        |   |                        |   |
|--------------------------------------------------------------------------------------------------------|---|------------------------|---|
| Airbag Driver Front                                                                                    | ✓ | Airbag Passenger Front | ✓ |
| ABS                                                                                                    | ✓ |                        |   |
|  <b>Exteriors</b>     |   |                        |   |
| Roof Rails                                                                                             | ✓ | Running Lights         | ✓ |
|  <b>Entertainment</b> |   |                        |   |
| Bluetooth Player                                                                                       | ✓ | Apple Play             | ✓ |
| Android Auto Play                                                                                      | ✓ |                        |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front right door

Panel: Light Scuffing < 50mm



Rear left door



Rear right door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm



### Fenders Condition

Left Fender



Right Fender

Right Fender: Paint Chip-off



### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



### Rear Bumper Condition

Rear Bumper

Rear Bumper: Fully Repainted, Replaced, Dent < 50mm, Light Scuffing < 80mm



### Hood Condition

Hood

Bonnet: Light Scuffing < 50mm



### Roof Condition

Roof



### Running Board Condition

Left Running Board



Right Running Board



### Windshield Condition

Front Windshield

Condition: Front Wiper blades need replacement



Rear Windshield

Wiper blade damaged



### Structural Assessment

Chassis Condition



Apron



|                              |   |                       |   |
|------------------------------|---|-----------------------|---|
| Boot Floor                   | ✓ | Firewall Condition    | ✓ |
| Head Light Support Condition | ✓ |                       |   |
| Cowl Top                     |   |                       |   |
| Cowl Top                     | ✓ |                       |   |
| Rear View Mirror Condition   |   |                       |   |
| Left Hand Side Mirror        | ✓ | Right Side Mirror     | ✓ |
| Alloy Wheel/ Rim             |   |                       |   |
| Left Front Alloy/ Rim        | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim       | ✓ | Right Rear Alloy/ Rim | ✓ |
| Grill Condition              |   |                       |   |
| Light Scuffing < 50mm        | ! | Monogram              | ✓ |
| Panel Condition              |   |                       |   |
| Rear Trunk Panel             | ✓ |                       |   |

## Engine & Transmission

|                        |   |                                |   |
|------------------------|---|--------------------------------|---|
| Engine                 |   |                                |   |
| Engine Performance     | ✓ | Engine Oil (Condition & Level) | ✓ |
| Exhaust System         | ✓ | Radiator Condition             | ✓ |
| Radiator Coolant       | ✓ |                                |   |
| Transmission Operation |   |                                |   |
| Gear Shifting          | ✓ | Drive Axle                     | ✓ |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid     | ✓ |                       |   |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

Keys

|                       |   |                         |   |
|-----------------------|---|-------------------------|---|
| Master Key            | ✓ |                         |   |
| Dashboard             |   |                         |   |
| Instrument Panel      | ✓ |                         |   |
| Controls              | ✓ | Cruise Control          | ✓ |
| Infotainment Display  | ✓ | Music System            | ✓ |
| Camera                | ✓ |                         |   |
| Lights                |   |                         |   |
| Headlight             | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster    | ✓ | Daylight Running Lights | ✓ |
| Air Conditioning      |   |                         |   |
| AC Cooling            | ✓ | AC System Leaks         | ✓ |
| Power/ Manual Windows | ✓ |                         |   |

## Interiors & Luggage

|                                                                |   |                              |   |
|----------------------------------------------------------------|---|------------------------------|---|
| Dashboard And Instrument Panel                                 |   |                              |   |
| Dashboard Upholstery: Minor Scuffing/<br>Disfiguration/ Melted | ! | Central Console              | ✓ |
| Cup Holder                                                     | ✓ | Steering Wheel               | ! |
|                                                                |   | Steering Wheel Fair Use Wear |   |
| Sunvisor                                                       | ✓ | Seat Upholstery              | ✓ |
| Manual Seat Movement                                           | ✓ | Seat Belts                   | ✓ |
| Head Rest                                                      | ✓ | Door Controls And Trim       | ✓ |
| Carpet                                                         |   | Headliner                    | ✓ |
| Front Left Floor Mat: Smudge/Burn/Crack                        | ! |                              |   |
| Rear View Mirror                                               | ! | Toolkit                      | ✓ |
| De Silvered Mirror<10%                                         |   |                              |   |

## Tyres

Tyres Condition

|                            |                                                                                   |                           |                                                                                     |
|----------------------------|-----------------------------------------------------------------------------------|---------------------------|-------------------------------------------------------------------------------------|
| Left Hand Side Front Tyre  |   | Left Hand Side Rear Tyre  |   |
| Right Hand Side Front Tyre |  | Right Hand Side Rear Tyre |  |
| Spare Tyre                 |  |                           |                                                                                     |
| Life remaining             |                                                                                   |                           |                                                                                     |
| LHS Front Tyre             | <75%                                                                              | LHS Rear Tyre             | <75%                                                                                |
| RHS Front Tyre             | <75%                                                                              | RHS Rear Tyre             | <75%                                                                                |
| Spare Tyre                 | <55%                                                                              |                           |                                                                                     |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE