

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2023 RENAULT DUSTER

PE | 87,251 KM

VIN: VF1HSRSCXPA057740

Car highlights

Four wheel drive

This car has a Four wheel drive

Cruise control

Cruise control to drive with ease & comfort

Bluetooth

Enjoy your drive with bluetooth

Amazing Comfort

Power driver seat

Basic Details

Kilometers	87251	Specs	Yes
Engine	2.0L	Option Type	Basic
Transmission	Automatic	Drive	Four Wheel Drive
Body Type	SUV	Fuel Efficiency	13.0 km/L mileage
Wheel Type	Alloy Wheels	Exterior Color	Exterior Color Blue
Interior Trim	Fabric Trim	Number of Airbags	2 Airbags
Seating Capacity	5 Seats	Number of keys	1 Keys
VIN number	VF1HSRSCXPA057740		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Exteriors			
Fog Light Front	✓	Roof Rails	✓
Running Lights	✓		
Comfort & Convenience			
Cruise Control	✓	Power Window front - Drivers Side	✓
Power Window front - Passenger Side	✓		

Entertainment			
Bluetooth Player	✓		
Safety & Security			
Airbag Driver Front	✓	Airbag Passenger Front	✓
ABS	✓		

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

Exterior

Doors condition

Front right door Panel: Light Scuffing < 50mm	Rear left door Panel: Scuffing
Rear right door Panel: Scuffing > 50mm	

Fenders Condition

Left Fender Condition: Scuffing	Right Fender Right Fender: Scuffing

Quarter Panels Condition

Left Quarter Panel	Right Quarter Panel Condition: Light Scuffing

Rear Bumper Condition

Rear Bumper Rear Bumper: Light Scuffing < 80mm, Crack/ Misaligned

Hood Condition

Hood

Running Board Condition

Left Running Board	Right Running Board

Sunroof Glass Condition (If Equipped)

Sun Roof Glass

Windshield Condition

Front Windshield	Rear Windshield

Structural Assessment

Chassis Condition	Boot Floor
Head Light Support Condition	

Cowl Top

Cowl Top

Alloy Wheel/ Rim

Left Front Alloy/ Rim

Left Rear Alloy/ Rim

Right Front Alloy/ Rim

Right Rear Alloy/ Rim

Panel Condition

Rear Trunk Panel

Engine & Transmission

Engine

Engine Body

Engine Performance

Engine Oil (Condition & Level)

Turbocharger/ Supercharger

Radiator Condition

Radiator Coolant

Transmission Operation

Gear Shifting

Drive Axle

4*4 Condition (If Applicable)

Steering, Suspension & Brakes

Steering

Steering wheel

Brake System

Parking Brake

Brake Master Cylinder

Suspension

Shock Absorbers

Electricals, Controls & Lights

Keys

Master Key

Dashboard

Instrument Panel

Controls

Infotainment Display

Music System	✓	Camera	✓

Lights

Headlight	✓	Tail Light Cluster	✓
Daylight Running Lights	✓		

Air Conditioning

AC Cooling	✓		
Power/ Manual Windows	✓	Memory Seats	✓

Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted	!	Central Console	✓
Steering Wheel	✓	Headliner	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Life remaining

LHS Front Tyre	<90%	LHS Rear Tyre	<90%
RHS Front Tyre	<90%	RHS Rear Tyre	<90%
Spare Tyre	<35%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE