



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



COMING SOON



2024 GAC EMKOO

GL | 51,619 KM

VIN: LMGAT1L81R1294206

Car highlights



Boosted Engine

This car has a Boosted Engine



Adaptive cruise control

Adaptive cruise control to drive with ease & comfort



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	51619	 Specs	Yes
 Engine	1.5L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	LMGAT1L81R1294206		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
Adaptive cruise control 		360 degree Camera 	
Lane Departure Warning System 		Parking Sensors Rear 	
Reverse Camera 		Collision Warning System 	
Front Camera 		Side Camera 	
Airbag Sides 		Airbag Curtain Shield 	

Airbag Driver Front	✓	Airbag Passenger Front	✓
ABS	✓		
 Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Tailgate/ Power Trunk	✓	Power Windows Rear	✓
 Exteriors			
Roof Rails	✓	Running Lights	✓
Rear Bumper Spoiler	✓		
 Entertainment			
Bluetooth Player	✓	Apple Play	✓

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door		Rear left door	
Panel: Light Scuffing < 50mm			

Rear right door			
Panel: Light Scuffing < 50mm			

Fenders Condition

Left Fender		Right Fender	
Condition: Light Scuffing			

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
		Condition: Light Scuffing	

Rear Bumper Condition

Rear Bumper			
Rear Bumper: Scuffing > 80mm			

Hood Condition

Hood			
Bonnet: Light Scuffing < 50mm			

Roof Condition

Roof			
------	---	--	--

Running Board Condition

Left Running Board		Right Running Board	
--------------------	---	---------------------	---

Sunroof Glass Condition (If Equipped)

Sun Roof Glass			
----------------	---	--	--

Windshield Condition

Front Windshield		Rear Windshield	
Condition: Front Wiper blades need replacement			

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Right Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	!	Right Rear Alloy/ Rim	✓
Rim: Alloy Face Scuffing			
Monogram	✓		
Panel Condition			
Rear Trunk Panel			
Dent	!		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key

Remote/Boot Not Opening



Dashboard

Instrument Panel



Controls



Cruise Control



Infotainment Display



Music System



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



Daylight Running Lights
Right DRL: Low Brightness



Air Conditioning

AC Cooling



AC System Leaks



Rear Blower Switch



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/
Disfiguration/ Melted



Central Console



Cup Holder



Steering Wheel
Steering Wheel Fair Use Wear



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Carpet

Front Left Floor Mat: Smudge/Burn/Crack



Headliner



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<75%

LHS Rear Tyre

<75%

RHS Front Tyre

<75%

RHS Rear Tyre

<65%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE