



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2020 BMW 520i**

**STD | 63,537 KM**

VIN: WBAJA1A04LWW35548

## **Car highlights**



### **Great condition**

Car has low imperfections



### **Cruise control**

Cruise control to drive with ease & comfort



### **Apple play**

Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat, Memory Seats

Basic Details

|                                                                                                    |                   |                                                                                                     |                     |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|---------------------|
|  Kilometers       | 63537             |  Specs             | Yes                 |
|  Engine           | 2.0L              |  Option Type       | Basic               |
|  Transmission     | Automatic         |  Drive             | Rear Wheel Drive    |
|  Body Type        | SEDAN             |  Fuel              | Petrol              |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Blue |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 4 Airbags           |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys              |
|  VIN number     | WBAJA1A04LWW35548 |                                                                                                     |                     |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |  |                                                                                     |                                   |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|--|-------------------------------------------------------------------------------------|-----------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |  |                                                                                     |                                   |                                                                                       |
| Climate Control AC                                                                                                   |  |  | Cruise Control                    |  |
| Memory Seats                                                                                                         |  |  | Power Window front - Drivers Side |  |
| Power Window front - Passenger Side                                                                                  |  |  | Power Windows Rear                |  |
|  <b>Exteriors</b>                 |  |                                                                                     |                                   |                                                                                       |
| Fog Light Front                                                                                                      |  |  |                                   |                                                                                       |



Safety & Security

Parking Sensors Front



Parking Sensors Rear



Reverse Camera



Airbag Curtain Shield



Airbag Driver Front



Airbag Passenger Front



ABS



Entertainment

Bluetooth Player



Apple Play



Android Auto Play



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

Doors condition

Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Running Board Condition

Left Running Board



Right Running Board



Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Boot Floor



Head Light Support Condition



Cowl Top

Cowl Top



Alloy Wheel/ Rim

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Left Front Alloy/ Rim  | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Panel Condition        |   |                       |   |
| Rear Trunk Panel       | ✓ |                       |   |

## Engine & Transmission

|                                              |   |                            |   |
|----------------------------------------------|---|----------------------------|---|
| Engine                                       |   |                            |   |
| Engine Body                                  |   |                            |   |
| Damage & Leaks: Tappet noise, Mountings weak | ! | Engine Performance         | ✓ |
| Engine Oil (Condition & Level)               | ✓ | Turbocharger/ Supercharger | ✓ |
| Radiator Condition                           | ✓ | Radiator Coolant           | ✓ |
| Transmission Operation                       |   |                            |   |
| Gear Shifting                                | ✓ | Drive Axle                 | ✓ |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Steering        |   |                       |   |
| Steering wheel  | ✓ |                       |   |
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

|                  |   |                      |   |
|------------------|---|----------------------|---|
| Keys             |   |                      |   |
| Master Key       | ✓ |                      |   |
| Dashboard        |   |                      |   |
| Instrument Panel | ✓ |                      |   |
| Controls         | ✓ | Infotainment Display | ✓ |
| Music System     | ✓ | Camera               | ✓ |
| Lights           |   |                      |   |

|                                    |   |                    |   |
|------------------------------------|---|--------------------|---|
| Headlight                          | ✓ | Tail Light Cluster | ✓ |
| Daylight Running Lights            | ✓ |                    |   |
| Air Conditioning                   |   |                    |   |
| AC Cooling                         | ! |                    |   |
| AC Temperature: Ac bad odor/ Smell |   |                    |   |
| Power/ Manual Windows              | ✓ | Memory Seats       | ✓ |

## Interiors & Luggage

|                                |   |                                          |   |
|--------------------------------|---|------------------------------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console                          | ✓ |
| Steering Wheel                 | ✓ | Headliner<br>Front Left: Headliner Loose | ! |

## Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | !    |                           |      |
| No                         |      |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <90% | LHS Rear Tyre             | <73% |
| RHS Front Tyre             | <90% | RHS Rear Tyre             | <73% |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE